



Occurrences Entered into the ATSB Maritime Safety Database
Between 18 August 2012 and 24 August 2012

Occurrence Date	ATSB Reference Number	Occurrence Time	Time Zone	Investigation	Location	Vessel Name	Identifier Type	Identifier	Occurrence Type	Summary
13/08/2012	MA201200113	18:30	UTC+10	No	Off NSW coast, Sydney	Cape Avila	IMO No	9167033	Damage to ship or equipment	Upon sounding tanks, after encountering heavy weather, it was found that #1S cargo tank was leaking into an adjacent, empty ballast tank. All other tanks were confirmed secure. The cargo tank was emptied and the ballast tank inerted. All tanks and surrounding waters were monitored closely until the ship could enter port and repairs could be made.
14/08/2012	MA201200116	0:01	UTC+10	No	Curtis Island, Gladstone port	Toll Dragonfly	IMO No	9550656	Grounding / stranding	While departing the Curtis Island loading ramp, as the landing barge manoeuvred clear of the ramp and into the swing area, it touched bottom. The barge was not stuck fast and after checking all systems were operational and tanks and spaces were sound it proceeded on its way without further incident.
15/08/2012	MA201200114	17:00	UTC+10	No	Burnie, Tasmania	Victorian Reliance	IMO No	9180205	Fire / explosion	On departing Burnie a small fire was found in the galley of the ship. The fire was in an electrical control box for a piece of galley equipment and the officer who discovered the fire quickly extinguished it with a Carbon Dioxide extinguisher. The ship continued on its voyage to Melbourne where further investigations and repairs were made. No injuries or other damage was reported.

Note: For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter that the ATSB has decided not to investigate, as identified in this publication, are not to be treated as OBR on and after the date of publication of this weekly summary.

Section 48 of the TSI Act contains a definition of an OBR. The voice component of a Voyage Data Recorder normally meets the requirements of an OBR.

Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBR. When an OBR is declared not to be an OBR other protections may continue to apply such as those relating to personal information under privacy legislation.