



Occurrences Entered into the ATSB Maritime Safety Database
Between 01 March 2014 and 07 March 2014

Occurrence Date	ATSB Reference Number	Occurrence Time	Time Zone	Investigation	Location	Vessel Name	Identifier Type	Identifier	Occurrence Type	Summary
01/03/2014	MA201400027	11:18	UTC+8	Yes - MO-2014-002	460 miles north-north-west of Dampier	Aquarosa	IMO No	9506708	Lifeboat accident	While conducting routine maintenance in the free fall lifeboat the boat was accidentally launched with one occupant on board. The lifeboat and the occupant were successfully recovered. The occupant suffered bruising to his head and limbs.

Note: For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter that the ATSB has decided not to investigate, as identified in this publication, are not to be treated as OBR on and after the date of publication of this weekly summary.

Section 48 of the TSI Act contains a definition of an OBR. The voice component of a Voyage Data Recorder normally meets the requirements of an OBR.

Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBR. When an OBR is declared not to be an OBR other protections may continue to apply such as those relating to personal information under privacy legislation.