

**Aviation Safety Investigation Report
199800374**

**Fairchild Industries Inc
Metro 23**

30 January 1998

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199800374 **Occurrence Type:** Incident
Location: 10km N Sydney, Aerodrome
State: NSW **Inv Category:** 4
Date: Friday 30 January 1998
Time: 1437 hours **Time Zone** ESuT
Highest Injury Level: None

Aircraft Manufacturer: Fairchild Industries Inc
Aircraft Model: SA227-DC
Aircraft Registration: VH-DMI **Serial Number:** DC-839B
Type of Operation: Air Transport Domestic Low Capacity Passenger Scheduled
Damage to Aircraft: Nil
Departure Point: Sydney NSW
Departure Time: 1432 ESuT
Destination: Armidale NSW

Approved for Release: Tuesday, July 7, 1998

