Aviation Safety Investigation Report 199000086

Robinson R22B

11 May 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199000086 Occurrence Type: Accident

Location: 60km W of Moola Bulla Station WA

Date: 11 May 1990 **Time:** 1000

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Robinson R22B

Registration: VH-LDE
Serial Number: 1283
Operation Type: Private
Damage Level: Substantial

Departure Point: Moola Bulla Station WA

Departure Time: Not Known

Destination: Moola Bulla Station WA

Approved for Release: 3rd July 1990

Circumstances:

There was a strong easterly wind blowing when the pilot landed. After landing he left the main rotor drive engaged and did not secure the collective control with the latch that was provided for that purpose. A sudden gust of wind caused the collective pitch, on the main rotor blades, to increase and the aircraft lifted off. The pilot regained control of the helicopter, but he was unable to avoid colliding with a tree.