**Aviation Safety Investigation Report 199603324** 

Piper Aircraft Corp Navajo Piper Aircraft Corp Chieftain

01 October 1996

## Aviation Safety Investigation Report 199603324

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199603324 Occurrence Type: Incident

**Location:** Cowes, VOR

VIC State: **Inv Category:** 

Date: Tuesday 01 October 1996

Time: Time Zone **EST** 1021 hours

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-31

VH-OZN Aircraft Registration: Serial Number: 31-285

**Type of Operation:** Air Transport Domestic Low Capacity Passenger Scheduled

**Damage to Aircraft:** Nil

Wynyard Tas **Departure Point:** 0730 EST **Departure Time: Destination:** Moorabbin Vic

Aircraft Piper Aircraft Corp

Manufacturer:

**Aircraft Model:** PA-31-350

Serial Aircraft Registration: VH-OZM 31-7852003

Number:

**Type of Operation:** Air Transport Domestic Low Capacity Passenger

Scheduled

**Damage to Aircraft:** Nil

**Departure Point: Devonport Tas** 

**Departure Time:** 

**Destination:** Moorabbin Vic

**Approved for Release:** Tuesday, October 15, 1996

VH-OZM and VH-OZN were on descent OCTA approaching Cowes. OZN was the leading and lower aircraft and both pilots were aware of and communicating with each other and the pilot of OZM had OZN in sight ahead and below. Both pilots were communicating with Melbourne Centre. When the two aircraft were on descent, the controller that he had lost the mode C altitude readout for OZN.

As they approached Cowes, the pilot of OZM diverted his attention to some cockpit duties. Shortly afterwards, he heard the pilot of OZN give his Cowes position report and at that time OZM was still four miles from Cowes by GPS. When the pilot of OZM next sighted OZN, after passing Cowes, the two aircraft were at the same level and laterally separated by approximately 100 metres.