



**Occurrences Entered into the ATSB Maritime Safety Database**  
**Between 23 February 2019 and 01 March 2019**

Occurrence Date	ATSB Reference Number	Occurrence Time	Time Zone	Investigation	Location	Vessel Name	Identifier Type	Identifier	Occurrence Type	Summary
22/02/2019	MA201900083	22:30	UTC+8	No	97 NM W Esperance	FALCON II	Fishing Registration	VNW5653	Foundered	While conducting offshore fishing operations, the crew discovered flooding in the engine room and steering compartment. The crew were unable to pump the water from the hull and the vessel subsequently foundered and sank.
23/02/2019	MA201900086	15:25	UTC+9.5	No	Adelaide	Popeye I ----- BBQ Buoys	Other	452308 ----- Unknown	Collision	The crew of the sight-seeing vessel observed the pleasure-craft approaching head on. The pleasure-craft failed to alter course and collided with the port bow of the sight-seeing vessel.
25/02/2019	MA201900085	4:30	UTC+8	No	Port Hedland	Navios Bonavis	IMO No	9446996	Machinery failure	While transiting from the anchorage to the berth, the main engine failed.
28/02/2019	MA201900090	12:00	UTC+11	No	Botany Bay	ANL Emora	IMO No	9362700	Machinery failure	During approach to the berth, the main engine stopped after a generator failed. The crew dropped anchor and a second tug was called to provide assistance. The generator and engine were restarted and the vessel continued to the berth.
28/02/2019	MA201900091	15:55	UTC+9	No	280 NM NW Darwin	Greyman Express	IMO No	9733777	Machinery failure	During ocean passage, the crew detected a main engine fuel pump fault. The crew shut down the main engine to allow the fuel pump to be replaced and passage was resumed approximately 11 hours later.

Note: For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter that the ATSB has decided not to investigate, as identified in this publication, are not to be treated as OBR on and after the date of publication of this weekly summary.

Section 48 of the TSI Act contains a definition of an OBR. The voice component of a Voyage Data Recorder normally meets the requirements of an OBR.

Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBR. When an OBR is declared not to be an OBR other protections may continue to apply such as those relating to personal information under privacy legislation.