



Occurrences Entered into the ATSB Maritime Safety Database  
Between 15 June 2019 and 21 June 2019

Occurrence Date	ATSB Reference Number	Occurrence Time	Time Zone	Investigation	Location	Vessel Name	Identifier Type	Identifier	Occurrence Type	Summary
20/06/2019	MA201900226	6:40	UTC+10	No	28 NM NW Cape Flattery	Sonja	IMO No	9344370	Machinery failure	During ocean passage, the vessel's main engine overheated and stopped. The vessel was anchored for repairs and resumed passage one hour later.

Note: For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter that the ATSB has decided not to investigate, as identified in this publication, are not to be treated as OBR on and after the date of publication of this weekly summary.

Section 48 of the TSI Act contains a definition of an OBR. The voice component of a Voyage Data Recorder normally meets the requirements of an OBR.

Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBR. When an OBR is declared not to be an OBR other protections may continue to apply such as those relating to personal information under privacy legislation.